## The City of North Little Rock

TOM WADLEY



701 WEST 29TH STREET

NORTH LITTLE ROCK, ARKANSAS 72114

501-791-8581 • Fax 501-791-8584

NLRCodeEnforcement@northlittlerock.ar.gov

## CODE ENFORCEMENT DEPARTMENT

June 26, 2019

Mayor Smith
City Council Members

Re:

5217 Chiquito Road

PT SE SE COM NE COR TH S330' W1124' MOL TH S50' TO POB CONT S50' TH W140' TH N50' TH E140' TO POB AKA Lot 2 Block 4 Overton Dub

UNREC PLAT 29-2N-11W Parcel 23N0270005800 North Little Rock, AR 72117

Parcel 23N0270005700

PT SE SE COM NE COR TH S330' W1124' MOL TO POB TH S50' TH W140' TH N50' TH E140' TO POB AKA Lot 1 Block 4 Overton Sub UNREC

PLAT 29-2N-11W

North Little Rock, AR 72117

Owner: Marguis Thompson

North Little Rock, AR

Dear Mayor Smith;


April 2019 I received a complaint regarding the dilapidated structure. I performed an exterior inspection which showed rotted, fascia, soffits, and broken windows. This structure has been vacant with the electric meter removed since February 2014 according to North Little Rock utility department.


Notice of City Council scheduled for July 22nd, 2019 hearing date was mailed by certified and regular mail to all interested parties and posted to the premises. Notice of hearing was also ran in local newspaper.


June 10<sup>th</sup>, 2019 an Administrative Search Warrant was obtained for an interior inspection. The warrant was executed June 10<sup>th</sup>, 2019. I inspected the property, which showed damage to the walls, ceilings, floors there is also damaged electrical and plumbing throughout.


The structure is considered to be unfit for human habitation and also a public nuisance, it is the recommendation of the North Little Rock Code Enforcement Department that this structure be considered for condemnation.


Laura Petty
Code Enforcement Officer
























06/11/2019 14:39

